

CITY OF SARATOGA SPRINGS NATURAL RESOURCES INVENTORY - ENVIRONMENTAL REMEDIATION SITES

Map ID	Site Name	Address	Type of Listing	State/Federal ID	Summary	Classification/Status
US EPA National Priority Listing (NPL) Superfund						
1	Niagara Mohawk Power Corp. Saratoga Springs Plant – Saratoga Springs Excelsior St. MGP	East Ave, Route 50 & Excelsior Ave	US EPA National Priority List (NPL) Superfund Site & State Superfund Program	NPL #: 110009302986 SSP: 546015	Site contamination is a result of the former manufactured gas plant (MGP) operations. While some areas have been remediated, according to the NYSDEC listing, persons who enter the site could come into contact with contaminated soils by walking, digging, or disturbing the soil. The groundwater contamination is not considered a public health concern because the area is serviced by public water, which is sourced from an area not affected by this contamination. Source: https://www.dec.ny.gov/cfm/xtapps/derexternal/haz/details.cfm?pageid=3	2 – Hazardous waste confirmed
NYS DEC / State Superfund Program (Inactive Hazardous Waste Disposal Sites)						
2	Saratoga Springs Landfill	Weible Avenue	State Superfund Program	546008	The landfill has been properly closed/capped under the Municipal Waste program, which reduces the potential for future environmental impacts. Additionally, an on-site methane gas collection and venting system is currently operating which reduces the possibility of landfill gas migrating off-site. A deed restriction is in effect. Source: https://www.dec.ny.gov/cfm/xtapps/derexternal/haz/details.cfm?pageid=3	4 – Site has been properly closed but requires ongoing monitoring
3	Saratoga Tree Nursery	431 Route 50 South	State Superfund Program	546043	Contaminated soils were removed from nearby properties and treated on the nursery property. There is an ongoing groundwater monitoring and maintenance program at the property. According to the NYSDEC, “there are currently no ongoing exposures to the public at this site”. Source: https://www.dec.ny.gov/cfm/xtapps/derexternal/haz/details.cfm?pageid=3	4 – Site has been properly closed but requires ongoing monitoring
4	S&S Friendly Laundry	57/59 Church Street	State Superfund Program	546056	Groundwater contamination was identified in the vicinity of this facility, likely associated with dry cleaning operations. This site has a “Potential” status because investigation plans are currently being developed. Source: https://www.dec.ny.gov/cfm/xtapps/derexternal/haz/details.cfm?pageid=3	P – Potential
5	Rickett’s Dry Cleaners	2017-19 Doubleday Ave	State Superfund Program	546058	According to the NYSDEC listing, soil and groundwater contamination have been identified at this former dry cleaning facility property. Contaminants identified include chlorinated volatile organic compounds (CVOCs). The site has a “potential” status because there is potential contamination and further investigation is needed before it can be listed on the State Superfund Database. According to the listing, “as information for this site becomes available, it will be reviewed by the NYSDOH to determine if site contamination presents public health exposure concerns.” Source: https://www.dec.ny.gov/cfm/xtapps/derexternal/haz/details.cfm?pageid=3	P – Potential
6	Saratoga Springs Rifle Range	5 Bliven Way	State Superfund Program	546059	Soil samples are being tested to determine whether antimony, copper, or lead is present in soils.	P - Potential
7	Skidmore College	815 North Broadway	State Superfund Program	546051	A small area (approximately 0.1 acre) of mercury contamination was identified. As of August 5, 2008, all Interim Remedial Measure (IRM) related work was completed, which included the removal of all impacted soil from the campus. Source: https://www.dec.ny.gov/cfm/xtapps/derexternal/haz/details.cfm?pageid=3	C - Completed
NYS DEC Superfund Program and Voluntary Cleanup Program (VCP)						
8	Van Raalte Knitting Mill	High Rock and Excelsior Ave	State Superfund Program & NYSDEC Voluntary Cleanup Program (VCP)	SSP: 546036 VCP: V00300	Contamination associated with the former operations on-site was identified and removed. The NYSDEC determined that there are no remaining environmental concerns associated with the former disposal of hazardous waste on the site. Source: https://www.dec.ny.gov/cfm/xtapps/derexternal/haz/details.cfm?pageid=3	C - Completed
9	Sharon Cleaners	48 Lincoln Ave	State Superfund Program & NYSDEC Voluntary Cleanup Program (VCP)	SSP: 546052 VCP: V00364	Contamination associated with dry cleaning operations was identified at and near this property. Remediation was completed and the NYSDEC deemed the site “no longer presents a significant threat to the environment”. Source: https://www.dec.ny.gov/cfm/xtapps/derexternal/haz/details.cfm?pageid=3	4 – Site has been properly closed but requires ongoing monitoring
NYS DEC Voluntary Cleanup Program (VCP)						
10	NM – Ballston Spa MGP	130 Milton Ave, Ballston Spa	NYSDEC Voluntary Cleanup Program (VCP)	V00487	Contamination associated with the former manufactured gas plant (MGP) on-site was identified in soil and groundwater at various levels located throughout the site and nearby parking lot and residential lot. Remediation has been completed at the site and surrounding properties. According to the NYSDEC, “contact with contaminated soil or groundwater is unlikely unless persons dig below the ground surface. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination.” Source: https://www.dec.ny.gov/cfm/xtapps/derexternal/haz/details.cfm?pageid=3	A - Active
11	NM – Saratoga Springs Lake Ave MGP	Lake Ave	NYSDEC Voluntary Cleanup Program (VCP)	V00475	Soil and groundwater cleanup efforts were completed on-site, however, limited amount of contamination associated with the former manufactured gas plant (MGP) operations remain. It is not expected that people will come into contact with the contamination because it is beneath clean fill and asphalt. Remaining groundwater contamination is not of concern because the area is serviced by public water. Source: https://www.dec.ny.gov/cfm/xtapps/derexternal/haz/details.cfm?pageid=3	C - Completed
NYS DEC Brownfield Cleanup Program (BCP)						
12	53 Putnam Street	53 Putnam Street	NYSDEC Brownfield Cleanup Program	C546057	Petroleum contaminated soil was removed from this property around 2002. The BCP application remains under review by the NYSDEC. Source: https://www.dec.ny.gov/cfm/xtapps/derexternal/haz/details.cfm?pageid=3	A - Active
NYS DEC Permitted Waste Facilities – Not Subject to Remediation						
13	Groff Land Clearing Debris Landfill	82 Brook Road	NPL NYSDEC Landfill	N/A	This facility is listed on the NYS Solid Waste Management Facilities mapper and is considered active. Waste types accepted at this facility include land clearing debris. No information related to any contamination is listed associated with this site. No additional information is included on the NYSDEC website. Source: https://data.ny.gov/Energy-Environment/Landfill-Solid-Waste-Management-Facilities-Map/afg5-7i6u	Active
14	Clarkie’s Auto Salvage	191 Geyser Road	NYSDEC Vehicle Dismantling facility	N/A	According to the NYS Vehicle Dismantling & Crushing mapper, this facility is active and located at 191 Geyser Road. Source: https://data.ny.gov/Energy-Environment/Vehicle-Dismantling-Crushing-Solid-Waste-Management/pzvp-y7tq	Active
15	Milton Transfer Station	503 Geyser Road	NYSDEC Transfer Station	N/A	According to the NYS Transfer Stations mapper, this facility is active and located at 503 Geyser Road. Waste types accepted at this facility include: land clearing debris, brush, branches. Trees, and stumps. Source: https://data.ny.gov/Energy-Environment/Transfer-Stations-Solid-Waste-Management-Facilitie/avuu-s8z3	Active
16	Plan-It Waste & Recycling, Inc.	274 Greenfield Ave	NYSDEC C&D Debris & Recycling Facility	N/A	According to the NYS Construction and Demolition (C&D) Debris Solid Waste Management Facilities mapper, this facility is active and located at 274 Greenfield Avenue. Waste types accepted at this facility include brick and unadulterated wood. Source: https://data.ny.gov/Energy-Environment/Construction-and-Demolition-C-D-Debris-Solid-Waste/hra5-yqwi	Active